

**Attachment B – Comprehensive Report
Thames-Coromandel District Council
8 November 2022**

Comprehensive Report: Description of Major Works – 29 & 30 May 2022

A significant rain event occurred in the Coromandel area on the 29th & 30th of May 2022. As a result of this Thames-Coromandel area had large number of slips ranging in size and a number of blocked drainage assets. There was no permanent reinstatement sites identified however a number of road closures and slips required to be cleared and cleaned up.

Data from the Waikato Regional Council rainfall gauges at Castle Rock & Pinnacles in the graph below shows in excess of 160mm in a 24 hour period on 29 & 30th May 2022.

« Back to map


0.0
mm

Matawai Stm - Hodder East Rd Castle Rock - Rainfall

Days since last decent rainfall: 0
Latest reading: 30 Jun 2022 13:00
Latest value (mm): 0.00

Date from:

Date to: [Select last 5 days](#)





[« Back to map](#)

Kauaeranga River - Pinnacles - Rainfall

Days since last decent rainfall: 0
Latest reading: 30 Jun 2022 13:00
Latest value (mm): 0.00

Date from

29/05/2022



Date to

30/05/2022



[Select last 5 days](#)




Table 1: Cost Summary

There was a large number of slips in varying sizes across the network. These included the following roads:

- Blackjack Road
- Colville Road
- Comers Road
- Kaimarama Road
- Kapowai Road
- Kauaeranga Valley Road
- Kennedy Bay Road
- Lees Road
- Old Coach Road
- Port Charles Road
- Puketui Valley Road
- Rangihau Road
- Tapu Coroglen Road
- Te Punga Road
- 309 Road
- Tuatēawa Road
- Wentworth Valley Road
- Wharf Road Colville

- Wyuna Bay Road

In particular the storm event caused road closures on the following roads:

- Tuateawa Road
- Kennedy Bay Road
- Kauaeranga Valley Road
- Old Coach Road

Initial Response			
Road	Location & Issue	Permanent Repair	Cost
Network Wide	Network wide slips & drainage asset clearing	N/A	\$108,000
Total Physical works Initial Response			\$108,000

Cashflows

Expenditure in the 2022/23 financial year will include;

Initial Response	\$108,000
Total	\$108,000

Initial Response Site Photos



Site 1 - Bluff Road



Site 2 - Tapu Coroglen Road



Site 3 – Tapu Coroglen Road



Site 4 – Tapu Coroglen Road



Site 5 – Tapu Coroglen Road



Site 6 – Old Coach Road



Site 7 - Old Coach Road



Site 8 – The 309 Road




Site 9 – Tuatēawa Road



Site 10 - Tuatēawa Road



Site 11 – Tuatēawa Road



Site 12 - Kennedy Bay Road